


FIG. 6







FIG. 3



START 160 -162 controlled stand alone Check Mode Wait for Evaluate the commands over status of I/O -170 164 the Control pins Interface 166 -Set the Registers Wait for RF signals (operates according to the registers) 168 -

FIG. 5




FIG. 7




FIG. 8